

FIG. 1
(prior art)

STROBE N+1

STROBE N

CLOCK




FIG. 2C

METHOD OF MEASURING DUTY CYCLE
Raoul J. Belleau
Serial No.: Not Yet Assigned
Docket No.: T0529.70016US00




FIG. 3